



Accurate Sensors Technologies



PS3000 Scanning System



Plug & Play, Simple to Install
Fully Automatic tracking
Manual Option of camera aiming
Allows for Continuous reliable
Temperature Measurement
Tracking of individual profile-
temperatures in Multi Cavity Die

Features:

Selection of scanning modes:

- Hottest point
- Smooth point
- Program point (pendulum mode)
- Continuous scanning (pendulum mode)

Adjustable scanning range up to $\pm 25^\circ$

Adjustable scanning step from 0.1° to 5°



Adjustable scanning time

Minimal working distance 1 meter

Maximal working distance target size
dependence

Metal Processing Application:

Profile, Billet, Strip and bar.



Misgav Industrial Park
Misgav 20174, ISRAEL
Tel: +972-4-9990025, Fax: +972-4-9990031
E-Mail: 3t@3t.co.il, Web: www.3t.co.il
Web: [www. accuratesensors.com](http://www accuratesensors.com)